

# An Inspection Report

for



12/03/2021



Home Inspection Chicago

**708-837-0837**

[michael@HomeInspectionChicago.com](mailto:michael@HomeInspectionChicago.com)

## Definitions

All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

|   |                  |  |
|---|------------------|--|
| 1 | Normal           | The system, item or component is in normal or typical condition.   |
| 2 | Normal (Limited) | The system, item or component is in normal or typical condition but accessibility or observations were limited as compared to other similar properties.  |
| 3 | Maintenance/FYI  | The system, item or component requires maintenance or typical home owner repair or, the note provided is for informational purposes.   |
| 4 | Service/Repair   | The system, item or component requires service, repair, replacement and/or maintenance. It is best to have the upgrades completed by a qualified professional.                                       |
| 5 | Safety Concern   | The system, item or component is a safety deficiency. Immediate repairs are recommended.   |
| 6 | Defective        | The system, item or component needs immediate repair, replacement or servicing. It is unable to perform its intended function and immediate repairs should be completed by a qualified professional. |
| 7 | Not Inspected    | The system, item or component was not inspected (inaccessible or safety concerns) as compared to other similar properties  |
| 8 | Not Present      | The system, item or component was not present as compared to other similar properties  |

1 2 3 4 5 6 7 8

## General Information

### CLIENT

Name:

File Number: 21 1203 01

Email:

Referred By:

### PROPERTY

Property Address

City State Illinois Zip

Type: Single family

Estimated Age:

Square Footage:

Bedrooms: 5

Baths: 3.5

Garage: 2 Car

Heating: Forced air (2)

AC: Central Air Conditioning (2) Electrical: Breaker

Roof: Hipped

Foundation: Basement (finished)

Water: Municipal

Sewage: Municipal

Utilities (On/Off):

Electricity: ☒ On ☐ Off

Water: ☒ On ☐ Off

Gas: ☒ On ☐ Off ☐ Not Present

Upgrades:

None

Client Concerns:

Nothing specific

### PROFESSIONALS

**Inspector:** Michael Pignotti

Inspector Name Michael Pignotti

Company Name Home Inspection Chicago

Home Inspection Chicago

708-837-0837

michael@HomeInspectionChicago.com

## General Information (Continued)

Buying Agent:

Listing Agent: Dual agency

---

MISCELLANEOUS

Inspection Date: 12/03/2021

Weather: Mostly sunny

Start Time: 2:00

Others Present: Client, Client's agent

Temperature: 83

End Time: 4:30

Week Day: Monday

Soil Conditions: Dry

Fee: \$400

Property Occupied: Yes

---

Living Space

Entry/hallway/stairs Living Space

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

- |     |                                     |                                     |                          |                          |                                     |                          |                          |                          |   |
|-----|-------------------------------------|-------------------------------------|--------------------------|--------------------------|-------------------------------------|--------------------------|--------------------------|--------------------------|---|
| 1.  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Ceiling: Drywall  |
| 2.  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Walls: Drywall  |
| 3.  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Floor: Carpeting, Hardwood, Area rug(s)                 |
| 4.  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Closet: Double  |
| 5.  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steps/Railing: Wood steps and handrail                  |
| 6.  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Doors: Metal  |
| 7.  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heating/Cooling: Forced Air                             |
| 8.  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Lighting & Switches: Conventional lighting and switches |
| 9.  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Outlets: Conventional outlets                           |
| 10. | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Smoke Detector: Present (not tested):                   |

Device(s) missing



Living room Living Space

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

- |     |                                     |                                     |                          |                          |                          |                          |                          |                          |                  |
|-----|-------------------------------------|-------------------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|------------------|
| 11. | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Ceiling: Drywall |
| 12. | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Walls: Drywall   |

## Living Space (Continued)

13. ☐☒☒☐☐☐☐☐☐ Floor: Hardwood and area rug(s):  
[Sun stained \(faded from exposure to sunlight\)](#)



14. ☐☐☒☐☐☐☐☐ Windows: Double hung:  
[Screen\(s\) missing](#)




15. ☒☐☐☐☐☐☐☐☐ Heating/Cooling: Forced Air  
 16. ☒☐☐☐☐☐☐☐ Lighting & Switches: Conventional switches - no lighting fixtures  
 17. ☐☒☐☐☐☐☐☐ Outlets: Conventional outlets  
 18. ☐☐☐☐☐☐☐☒ Smoke Detector:

Dining room Living Space

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

19. ☒☐☐☐☐☐☐☐ Ceiling: Drywall  
 20. ☐☐☒☐☐☐☐☐ Walls: Drywall, Wallpaper:  
[Amateur wallpaper application](#)



## Living Space (Continued)

21. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Floor: Hardwood and area rug(s)



22. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Windows: Double hung:  
Screen(s) missing

23. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Heating/Cooling: Forced Air

24. ☐ ☐ ☐ ☒ ☐ ☐ ☐ ☐ Lighting & Switches: Conventional lighting and switches:  
Lighting not working

25. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Outlets: Conventional outlets

26. ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☒ Smoke Detector:

Family room Living Space

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

27. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ceiling: Drywall

28. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Walls: Drywall

29. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Floor: Carpeting

30. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Windows: Double hung

31. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Heating/Cooling: Forced Air

32. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Lighting & Switches: Conventional lighting and switches, Conventional lighting

33. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Outlets: Conventional outlets

34. ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☒ Smoke Detector:

## Bedroom

Master Bedroom

1. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ceiling: Drywall

2. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Walls: Drywall

3. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Floor: Carpeting

4. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Doors: Wood

5. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Windows: Double hung

6. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Closet: Walk in

7. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Heat/Cool: Forced Air

8. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Lighting & Switches: Conventional lighting, ceiling fan and switches

9. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Outlets: Conventional outlets

10. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Smoke Detector: Present (not tested)

Pink Bedroom

11. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ceiling: Drywall

12. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Walls: Drywall

13. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Floor: Carpeting

14. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Doors: Wood

15. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Windows: Double hung

16. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Closet: Walk in

17. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Heat/Cool: Forced Air

## Bedroom (Continued)

18. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Lighting & Switches: Conventional lighting, ceiling fan and switches  
 19. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Outlets: Conventional outlets  
 20. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Smoke Detector: Present (not tested)

## Red Bedroom

21. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ceiling: Drywall  
 22. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Walls: Drywall  
 23. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Floor: Carpeting  
 24. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Doors: Wood:  
     Door binds in framing



25. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Windows: Double hung  
 26. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Closet: Double  
 27. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Heat/Cool: Forced Air  
 28. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Lighting & Switches: Conventional lighting, ceiling fan and switches  
 29. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Outlets: Conventional outlets  
 30. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Smoke Detector: Present (not tested)

## Aqua Bedroom

31. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ceiling: Drywall  
 32. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Walls: Drywall  
 33. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Floor: Carpeting  
 34. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Doors: Wood  
 35. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Windows: Double hung  
 36. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Closet: Walk in  
 37. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Heat/Cool: Forced Air  
 38. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Lighting & Switches: Conventional lighting, ceiling fan and switches  
 39. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Outlets: Conventional outlets  
 40. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Smoke Detector: Present (not tested)

## 1st floor Bedroom

41. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ceiling: Drywall  
 42. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Walls: Drywall  
 43. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Floor: Carpeting  
 44. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Doors: Wood  
 45. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Windows: Double hung  
 46. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Closet: Double  
 47. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Heat/Cool: Forced Air  
 48. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Lighting & Switches: Conventional lighting and switches  
 49. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Outlets: Conventional outlets  
 50. ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☒ Smoke Detector:



## Kitchen

## 1st floor Kitchen

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

1. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ceiling: Drywall  
 2. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Walls: Drywall  
 3. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Floor: Hardwood  
 4. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Doors: Wood frame with glass  
 5. ☐ ☐ ☐ ☒ ☐ ☐ ☐ ☐ Windows: Double hung:

Seal(s) broken: the space between the panes of glass is broken allowing dirt and debris to "cloud" view - the only remedy is replacement



6. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Lighting & Switches: Conventional lighting, ceiling fan and switches  
 7. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Outlets & GFCI's: Conventional outlets, GFCI(s)  
 8. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Heating/Cooling: Forced Air  
 9. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Pantry: Walk in  
 10. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Countertops: Laminate  
 11. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Cabinets: Wood  
 12. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Faucets: Manufacturer not determined  
 13. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Sink: Stainless steel  
 14. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Supply lines/Drain: Copper supply with PVC drainage:  
 Leaking (yellow oval)



15. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Disposal: Kenmore  
 16. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Dishwasher: Kenmore  
 17. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Refrigerator: General Electric

## Kitchen (Continued)

18. ☐☐☒☐☐☐☐☐ Cooking Appliances: Kenmore:  
[Verify that anti-tip bracket is present and installed properly](#)



19. ☒☐☐☐☐☐☐☐ Microwave: General Electric



20. ☒☐☐☐☐☐☐☐ Ventilator: General Electric

## Bathroom

## Master Bathroom

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

1. ☐☐☒☐☐☐☐☐ Ceiling: Drywall:  
[Unusual pattern or stain on ceiling - discuss with owner](#)



2. ☒☐☐☐☐☐☐☐ Walls: Drywall  
 3. ☒☐☐☐☐☐☐☐ Floor: Tile and area rug(s)  
 4. ☒☐☐☐☐☐☐☐ Doors: Wood  
 5. ☒☐☐☐☐☐☐☐ Windows: Double hung, Skylight(s)  
 6. ☒☐☐☐☐☐☐☐ Closet: Linen  
 7. ☒☐☐☐☐☐☐☐ Heating/Cooling: Forced Air  
 8. ☒☐☐☐☐☐☐☐ Lighting & Switches: Conventional lighting & switches  
 9. ☒☐☐☐☐☐☐☐ Outlets & GFCI's: GFCI(s)



## Bathroom (Continued)

10. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Ventilation: Fan:  
[See "Bathroom Vents" in Attic category](#)
11. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Mirror: Wall mounted
12. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Countertop: Engineered materials
13. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Vanity | Cabinetry: Wood
14. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Faucet: Manufacturer not determined
15. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Sink: Engineered materials (2)
16. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Supply lines/Drain: Copper supply with metal drain:  
[Faucet handle spins \(yellow oval\) - does not come to a stop](#)

[Drainage slow \(yellow arrow\)](#)



17. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Toilet: Kohler
18. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Shower: Plastic surround
19. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Spa Tub: Plastic:  
[Access panel for mechanicals in bedroom \(yellow oval\)](#)



## 2nd floor Bathroom

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

20. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ceiling: Drywall
21. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Walls: Drywall
22. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Floor: Tile and area rug(s)
23. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Doors: Wood
24. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Windows: Skylight(s)
25. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Heating/Cooling: Forced Air

## Bathroom (Continued)

26. ☐☐☐☒☐☐☐☐ Lighting & Switches: Conventional lighting & switches:  
Lighting not working



27. ☒☐☐☐☐☐☐☐ Outlets & GFCI's: GFCI(s)

28. ☐☒☐☐☐☐☐☐ Ventilation: Fan:

[See "Bathroom Vents" in Attic category](#)

29. ☒☐☐☐☐☐☐☐ Mirror: Wall mounted

30. ☒☐☐☐☐☐☐☐ Countertop: Engineered materials

31. ☒☐☐☐☐☐☐☐ Vanity | Cabinetry: Wood

32. ☒☐☐☐☐☐☐☐ Faucet: Moen

33. ☒☐☐☐☐☐☐☐ Sink: Engineered materials

34. ☒☐☐☐☐☐☐☐ Supply lines/Drain: Copper supply with metal drain

35. ☒☐☐☐☐☐☐☐ Toilet: Kohler

36. ☐☐☒☐☐☐☐☐ Tub: Steel (porcelain finish):

[Caulk around faucet to prevent water from entering wall cavity](#)



37. ☒☐☐☐☐☐☐☐ Shower: Tile

Hallway (half) Bathroom

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

38. ☒☐☐☐☐☐☐☐ Ceiling: Drywall

39. ☒☐☐☐☐☐☐☐ Walls: Drywall

40. ☒☐☐☐☐☐☐☐ Floor: Hardwood and area rug(s)

41. ☒☐☐☐☐☐☐☐ Doors: Wood

42. ☐☐☐☐☐☐☐☒ Heating/Cooling:

43. ☒☐☐☐☐☐☐☐ Lighting & Switches: Conventional lighting & switches

44. ☒☐☐☐☐☐☐☐ Outlets & GFCI's: GFCI(s)

45. ☐☒☐☐☐☐☐☐ Ventilation: Fan:

[See "Bathroom Vents" in Attic category](#)

46. ☒☐☐☐☐☐☐☐ Mirror: Wall mounted

47. ☒☐☐☐☐☐☐☐ Faucet: Moen

48. ☒☐☐☐☐☐☐☐ Sink: Pedestal

## Bathroom (Continued)

49. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Supply lines/Drain: Stainless supply and metal drainage  
 50. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Toilet: Kohler

Lower level Bathroom

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

51. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ceiling: Drywall  
 52. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Walls: Drywall  
 53. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Floor: Tile (ceramic)  
 54. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Doors: Wood  
 55. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Heating/Cooling: Forced Air  
 56. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Lighting & Switches: Conventional lighting & switches  
 57. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Outlets & GFCI's: GFCI(s)  
 58. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ventilation: Fan:  
     [See "Bathroom Vents" in Attic category](#)  
 59. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Mirror: Wall mounted  
 60. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Countertop: Engineered materials  
 61. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Vanity | Cabinetry: Wood  
 62. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Faucet: Moen  
 63. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Sink: Engineered materials  
 64. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Supply lines/Drain: Stainless supply and PVC drainage  
 65. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Toilet: Kohler

## Fireplace

Family room Fireplace

1. Type: Natural gas  
 2. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Fireplace Construction: Brick  
 3. ☐ ☐ ☐ ☐ ☒ ☐ ☐ ☐ ☐ Glass Doors/Screen: Screen only:

**Screens do not prevent all embers from escaping the firebox and risks contact with combustible materials (yellow arrow)**

**Glass doors missing - installing this component adds a layer of fire safety which limits embers from contacting combustible materials. Doors will also limit or decrease air drafts**



4. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Firebox: Block  
 5. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Mantel: Wood

## Fireplace (Continued)

6. ☐☐☐☐☒☐☐☐☐ Hearth: Raised:  
Caulk missing



7. ☒☐☐☐☐☐☐☐☐ Damper: Iron  
8. ☐☒☐☐☐☐☐☐☐ Flue/Smoke Chamber: Brick  
9. ☐☒☐☐☐☐☐☐☐ Clean Out: Ashpit  
10. ☒☐☐☐☐☐☐☐☐ Gas Starter/Supply: Black pipe

## Laundry Area

1st floor Laundry Room/Area

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

1. ☒☐☐☐☐☐☐☐☐ Ceiling: Drywall  
2. ☐☒☐☐☐☐☐☐☐ Walls: Drywall  
3. ☒☐☐☐☐☐☐☐☐ Floors: Vinyl (sheet), Area rug(s)  
4. ☒☐☐☐☐☐☐☐☐ Doors: Wood  
5. ☐☒☐☐☐☐☐☐☐ Closet: Double  
6. ☒☐☐☐☐☐☐☐☐ Lighting & Switches: Conventional lighting and switches  
7. ☐☒☐☐☐☐☐☐☐ Outlets & GFCI's: Conventional outlet(s)  
8. ☒☐☐☐☐☐☐☐☐ Heating/Cooling: Forced air  
9. ☐☒☐☐☐☐☐☐☐ Countertops: Laminate  
10. ☒☐☐☐☐☐☐☐☐ Cabinets: Wood  
11. ☒☐☐☐☐☐☐☐☐ Laundry Tub: Plastic  
12. ☒☐☐☐☐☐☐☐☐ Supply lines/Drain: Copper supply with metal drain  
13. ☐☒☐☐☒☐☐☐☐ Washer: Kenmore:  
Mold (yellow arrow)

Front load washer: newer models have been know to have strong odors - recommend keeping door ajar and any trays open so moisture evaporates. Also, review manufacturer instructions and maintenance guidelines

Clothes inside - not operated

# Laundry Area (Continued)

Washer: (continued)




14. ☐☐☒☐☐☐☐☐ Hoses: Rubber: Rubber hoses have a tendency to leak - recommend replacing with braided supply hoses

Automatic washing machine water shut off valve recommended: if the current set-up develops a leak water will continue to flow since the valve is open. Installing an automatic shut off valve opens and closes the valve as needed



15. ☐☒☐☐☐☐☐☐ Washer Drain: Wall mounted drain  
16. ☒☐☐☐☐☐☐☐ Dryer: Maytag



17. ☐☒☐☐☐☐☐☐ Dryer Vent: Metal flex  
18. ☐☒☐☐☐☐☐☐ Dryer Gas Line: Flex

## Basement

## Lower level Basement

1. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Unable to Inspect: 40%:  
     [Finish materials obstructing view\(s\)](#)
2. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ceiling: Ceiling tiles, Drywall
3. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Joists: 2 x 10
4. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Sill Plates: Wood
5. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Beams: Steel
6. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Piers/Posts: Steel column(s)
7. ☐ ☒ ☒ ☐ ☐ ☐ ☐ ☐ Foundation: Concrete:


[Cold joint\(s\): the result of two or more separate pours. It is best for all the concrete to be poured at one time. Cold joints can leak and can weaken the concrete though it usually does not adversely affect the structure - recommend monitoring for any leaks, changes or movement in this area and consider obtaining an analysis by a structural engineer](#)



8. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Walls: Drywall
9. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Floors: Carpeting
10. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Doors: Wood:  
     [Door missing?](#)



11. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Windows: Hopper:  
     [Screen\(s\) missing](#)





## Basement (Continued)

12. ☐☐☐☐☒☐☐☐ Stairs/Railings: Wood steps:  
Handrail(s) missing (very common) - recommend installing



13. ☒☐☐☐☐☐☐☐ Heating/Cooling: Forced air  
 14. ☐☒☐☐☐☐☐☐ Ducts: Rigid  
 15. ☒☐☐☐☐☐☐☐ Lighting & Switches: Conventional lighting and switches  
 16. ☐☒☐☐☐☐☐☐ Outlets & GFCI's: Conventional outlet(s)  
 17. ☐☐☐☐☒☐☐☐ Smoke Detector: Wiring only:  
Device(s) missing



18. ☐☒☒☐☐☐☐☐ Insulation: Fiberglass:  
Verify that insulation is present - discussed with owner  
 19. ☒☐☐☐☐☐☐☐ Moisture/Location: None seen

## Heating

## Basement Furnace

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

1. Manufacturer: Amana Type: Forced air Area Served: All areas  
 2. Capacity listed (input/output) 80,000/64,000  
 Square Footage: 3000  
 3. ☒☐☐☐☐☐☐☐ Capacity needed: 120,000 Btu's  
 4. ☒☐☐☐☐☐☐☐ Age: 2017 - 1 year old

## Heating (Continued)

Age: (continued)



5. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Operation: Functional  
 6. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Thermostat: Electronic  
 7. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Jacket: Conventional  
 8. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Plenum/Ducts: Rigid  
 9. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Evaporative Coil (AC system): Copper core with metal fins  
 10. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Humidifier: Aprilaire:

Damper door to remain open during heating season and closed during cooling season:  
 failure to close damper in cooling season can result in an iced or frozen evaporative coil



11. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Combustion Chamber: 4 Burners



12. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Draft Hood/Fan: Fan:

Not fastened (yellow ovals) - best if sheet metal screws are used to fix draft hood which will prevent unhealthy gases from escaping into living spaces

Draft was checked using a "smoke pen" and was okay (yellow arrow)

## Heating (Continued)

Draft Hood/Fan: (continued)



13. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Flue Pipe: Single wall  
 14. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Chimney: Double walled pipe  
 15. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Blower Fan: Squirrel cage  
 16. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Fuel Line: Black pipe



17. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Filter: Electronic



18. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Safety Shut Off: Switch  
 19. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Carbon Monoxide Check: Monoxor II used



20. ☐ ☐ ☐ ☐ ☒ ☐ ☐ ☐ Carbon Monoxide Detectors: Not present:  
 Missing - recommend installing appropriate detectors

## Heating (Continued)

21. ☐☐☒☐☐☐☐☐ Condensate Removal (AC system): PVC:  
[Poorly routed in front of access panel](#)



2nd floor Furnace

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

22. Manufacturer: Bryant Type: Forced air Area Served: All areas  
 23. Capacity listed (input/output) See note above for first unit Square Footage: See note above for first unit  
 24. ☒☐☐☐☐☐☐☐ Capacity needed: See note above for first unit  
 25. ☐☒☒☐☐☐☐☐ Age (using ANSI date): 17 - ANSI year 1999: [Unit approaching the end of its useful service life - most units last 15-20 years](#)



26. ☒☐☐☐☐☐☐☐ Operation: Functional  
 27. ☒☐☐☐☐☐☐☐ Thermostat: Electronic  
 28. ☐☒☐☐☐☐☐☐ Jacket: Conventional  
 29. ☐☒☐☐☐☐☐☐ Plenum/Ducts: Rigid  
 30. ☐☒☐☐☐☐☐☐ Evaporative Coil (AC system): Copper core with metal fins  
 31. ☐☐☒☐☐☐☐☐ Humidifier: Aprilaire:  
[Damper door \(yellow arrow\) to remain open during heating season and closed during cooling season: failure to close damper in cooling season can result in an iced or frozen evaporative coil](#)

[Discharge tube \(lime arrow\) dirty \(know source of air borne bacteria\) - recommend replacing](#)

[Filter scaled \(pink arrow\) - replace](#)

[Condensation leaking \(lime and blue ovals\)](#)




## Heating (Continued)

40. ☒☐☐☐☐☐☐☐ Carbon Monoxide Check: Monoxor II used



41. ☐☐☐☐☒☐☐☐ Carbon Monoxide Detectors: Not present:  
     Missing - recommend installing appropriate detectors
42. ☐☐☒☐☐☐☐☐ Condensate Removal (AC system): PVC:  
     Poorly router in front of access panel




## Air Conditioning

## Exterior - North Air Conditioning

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

1. Type: Central air conditioning      Area Served: All areas
2. Square Footage: 3,000      Btu's Needed: 60,000 Btu's      Tonnage Needed: 5.0 tons
3. ☒☐☐☐☐☐☐☐ Tonnage Installed: 2.5 tons each
4. ☒☐☐☐☐☐☐☐ Age: 2009 - 9 years old



5. ☒☐☐☐☐☐☐☐ Operation: Functional
6. ☒☐☐☐☐☐☐☐ Condenser (exterior unit): Goodman
7. ☒☐☐☐☐☐☐☐ Electrical Disconnect: Pull plug
8. ☒☐☐☐☐☐☐☐ Refrigerant Lines: Liquid & suction lines



## Electrical

## Basement Electric Panel

1. ☐☐☒☐☐☐☐☐

Panel: Square D:

Panels are best mounted on plywood sheet (3/4"), not scrap lumber - monitor and consider repairs if panel loosens or if moisture enters. Typically, not cost effective to repair unless necessary

2. ☒☐☐☐☐☐☐☐☐☐

Amperage: 200 amps

3. ☒☐☐☐☐☐☐☐☐☐

Main Disconnect &amp; Entrance Cables: 200 Amps


4. ☒☐☐☐☐☐☐☐☐☐

Main Disconnect Location: At main panel

5. ☐☐☐☐☒☐☐☐☐☐


Breakers: Single and double pole:

Double tap(s) WITHOUT availability of unused breaker(s): breakers are designed to have one conductor (wire) connected to it. A second wire connected to the lug (screw) is called a double tap and increases the chance of loosening the lug. Loose connections can arc (spark) and start an electrical fire - double taps are not advised and repairs are recommended

6. ☐☐☐☐☒☐☐☐☐☐


Branch Circuits: Conduit:

Conductor(s) improperly sized to breaker(s) - #14 on 20amp: each breaker is designed to correspond with a properly sized conductor. Undersized conductors and oversized breakers increase the risk of electrical failure and fire - recommend repairs by a licensed electrician



## Electrical (Continued)

7. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Ground: Plumbing ground, Grounding rod



## Plumbing

### Main Plumbing Supply & DWV

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

1. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Service Line: Copper  
2. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Main Water Shutoff: At meter




3. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Water Lines: Copper  
4. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Drain Pipes: Cast iron  
5. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Vent Pipes: Cast iron  
6. ☐ ☐ ☐ ☐ ☐ ☐ ☒ ☐ Cleanouts: Inaccessible  
7. ☐ ☒ ☒ ☐ ☐ ☐ ☐ ☐ Floor Drain: Surface drain:

[Recommend flushing drain with water to reseal the trap and prevent sewer gas orders from entering the living space](#)

8. ☐ ☒ ☒ ☐ ☐ ☐ ☐ ☐ Gas Service Lines: Black pipe:

[Galvanic action: electrolytic corrosion \(electrolysis\) occurs when two dissimilar metals are in contact. The unlike metals cause a chemical reaction that results in the deterioration of one of them, Granted, the process may takes years but it will likely occur. Check for others...](#)



## Plumbing (Continued)

9. Radon mitigation system present? ☐ Yes ☒ No

Basement Water Heater

10. Manufacturer: AO Smith Type: Natural gas

Area Served: All areas

11. Capacity/Recovery Rate: 74 gallons/72.82 recovery rate Recovery rate: Recovery rate: buying water heaters base on tank capacity is misleading. These appliances should be purchased based on the "recovery rate" which is defined as how many gallons can be heated 90 degrees in one hour. In other words, if entry water into the water heater is 50 degrees then the recovery rate is how many gallons the unit can heat to 140 degrees in one hour

12. Recovery rate: buying water heaters base on tank capacity is misleading. These appliances should be purchased based on the "recovery rate" which is defined as how many gallons can be heated 90 degrees in one hour. In other words, if water entering the appliance is 50 degrees then the recovery rate is how many gallons the unit can heat to 140 degrees in one hour

13. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Operation: Functional

14. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Tank: Conventional

15. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Age: 2016 - 2 years old



16. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Draft Hood/Fan: Standard metal draft hood:

Not fastened (yellow ovals) - best if sheet metal screws are used to fix draft hood which will prevent unhealthy gases from escaping into living spaces

Draft was checked using a "smoke pen" and was okay (yellow arrow)



17. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Flue Pipe: Single wall


18. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Water Lines: Copper

19. ☐ ☐ ☐ ☐ ☒ ☐ ☐ ☐ T/P Valve & Drain Tube: Brass valve:

Discharge pipe opening is not within six inches of the floor

## Plumbing (Continued)

T/P Valve &amp; Drain Tube: (continued)



20. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Thermostat: Dial  
 21. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Drain: Screw type  
 Basement (at foundation wall) Sump  
 22. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Pump: Submerged  
 23. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Pit: Plastic  
 24. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Drain Piping: PVC  
 25. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Outlet: Dedicated circuit  
 26. ☐ ☒ ☒ ☐ ☐ ☐ ☐ ☐ Backup System: Not present: [Ask home owner if back up system is included in purchase](#)  
 Basement (at bathroom) Ejector  
 27. ☐ ☒ ☐ ☐ ☒ ☐ ☐ ☐ Pump: Submerged:

**Completely inaccessible (remove shelving unit)**



28. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Pit: Plastic  
 29. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Drain Piping: PVC  
 30. ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☒ Outlet: Inaccessible:  
     [Dedicated circuit missing?: this electrical supply should be solely for the sump pump in order to limit power overloads/failures - recommend repairs by a licensed plumbing contractor](#)  
 31. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Backup System: Not present: [Back up systems are encouraged as they prevent costly repairs from water damage. Battery back up systems are common and are not too expensive. They are limited though to the charge on the battery. However, water pressure backup systems do not use or need electricity to perform. As the name implies water pressure is used to drain the pit in the event of an emergency. They are more expensive but "battery life" is no concern. Sump and/or ejector backup systems are recommended to protect system, components and personal property](#)

## Attic

## 2nd level Attic

1. Method of Inspection: Access panel  
 2. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Unable to Inspect: 35%:  
     No floor decking  
 3. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Access Panel: Hardboard: Skirt missing (yellow arrow): a perimeter barrier or skirt is typically installed at panel opening to prevent blown/loose insulation from falling from opening

Panel(s) not insulated: excessive heat loss (or heat gain) can pass through in uninsulated area - installing insulation over the panel opening or framing, not solely the panel, will eliminate a void in the insulation blanket



4. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Roof Sheathing: Plywood  
 5. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Framing: Rafter 2x8  
 6. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Floor Decking: Plywood  
 7. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Floor Joists: 2 x 8  
 8. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ HVAC Ducts: Flex, Insulated  
 9. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Attic Ventilation: Roof and soffit vent(s)  
 10. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Plumbing Vent(s): Cast iron  
 11. ☒ ☒ ☒ ☒ ☐ ☐ ☐ ☐ Bathroom Vent(s): Not seen:

Bath vent(s) not visible: some contractors will install the vent between the attic floor joists and terminate it at a soffit vent. This also insulates the venting. This should be a dedicated vent and not shared as soffit vents are intended to allow air in which is contrary to bathroom fan venting. It is important to vent bathroom air to the outside because excessive moisture can cause a number of problems including damage to the structure, insulation and be a contributing cause of mold growth. It is also possible that the bathroom vent(s) are missing in which further review is recommended

12. ☒ ☒ ☒ ☒ ☐ ☐ ☐ ☐ Appliance Venting: Kitchen hood: Appliance vent(s) not visible: some contractors will install the vent(s) between the attic floor joists and terminate it at a soffit vent. This also insulates the venting. There should be a dedicated vent that is not shared because soffit vents are intended to allow air in which is contrary to bathroom fan venting. It is important to vent appliances to the outside because excessive moisture can cause a number of problems including damage to the structure, insulation and be a contributing cause of mold growth. It is also possible that the appliance vent(s) are missing in which further review is recommended
13. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Lighting & Wiring: Conventional lighting:  
     Lighting not working (bulbs?)
14. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Chimney (attic view): Metal pipe:  
     Combustion clearances inadequate (very common) - move insulation so it is not touching chimney

## Attic (Continued)

Chimney (attic view): (continued)

15. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Insulation: Fiberglass (batts), Cellulose16. ☒ ☒ ☒ ☐ ☐ ☐ ☐ ☐ Insulation Depth: 6-9":

Enough insulation to achieve an "R value" of 38 is recommended - most properties do not have the recommended amount of insulation

17. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Vapor Barrier: Kraft paper18. ☒ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Moisture Penetration: None seen

## Exterior &amp; Grounds

Main Exterior Surface

1. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Siding: Brick2. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Trim & Soffits: Aluminum3. ☒ ☒ ☒ ☐ ☐ ☐ ☐ ☐ Windows: Double hung:

Mortar joint(s) likely to deteriorate over time (yellow oval): this is an excellent way for water and air to infiltrate the wall cavity - when needed, repair mortar to 1/4" of surface and top with high quality sealant. Do not create groove (finger swipe) with sealant as water will not drain on flat horizontal surface

Masonry is reverse pitched: water will flow towards the window instead of away - recommend repairs

4. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Doors: Metal5. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Steps: Concrete6. ☐ ☒ ☒ ☐ ☐ ☐ ☐ ☐ Walks: Concrete:

Settled, consider mud-jacking: this process lifts or levels sunken concrete slabs. Holes are drilled through the slab and a concrete "slurry" is pumped under the slab until it levels out. The pumped liquid eventually hardens and the holes are patched



## Exterior & Grounds (Continued)

Walks: (continued)



7. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Driveway: Concrete  
 8. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Foundation: Concrete  
 9. ☐ ☐ ☐ ☐ ☒ ☐ ☐ ☐ Window Wells: Locked:

Not readily accessible in the event of an emergency (yellow arrows)

Window well cover(s) should be rigid to support someone walking in the area (lime arrow)

Add rock/fill (pink arrow) - promotes better drainage



10. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Fencing: Composite/plastic  
 11. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Grading: Minor slope  
 12. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Vegetation: Trees and shrubs:  
 Tree limbs too close to the roof - trim to avoid limbs from damaging roof surface  
 13. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Patio: Concrete  
 14. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Service Cables/Mast/Meter: Standard utility meter

## Exterior &amp; Grounds (Continued)

15. ☐ ☒ ☐ ☒ ☐ ☐ ☐ ☐ Lighting & Switches: Conventional lighting:  
 Lighting not working



16. ☐ ☐ ☐ ☒ ☐ ☐ ☐ ☐ Outlets & GFCI's: GFCI(s):  
 GFCI(s) does not respond to mechanical tester: device may be defective or miswired - recommend repairs



17. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Gas Meter: Exterior - North:  
 Surface rust: this condition will only get worse and possibly cause a gas leak - consideration should be given to replacing the piping or at least sealing it with a rust inhibitor



18. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Main Gas Valve: Located at gas meter

19. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Hose Bibs: Present:  
 Manifold for sprinkler system missing - discuss with owner



## Roof &amp; Chimney

## Main Roof Surface

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

1. Type: Flat Method of Inspection: Roof (on surface)

2. ☒ ☒ ☐ ☐ ☐ ☐ ☐ ☐ Roof Surface: Shingles:

Algae/fungi/moss (darker areas/streaks) on shingles (yellow arrow): this growth limits the drying process and accelerates aging - recommend using the appropriate methods to remove and clean area. Installing zinc strips at the ridge is a popular choice to remove algae as it does not flourish when the metal is present

Fiberglass mat or core exposed (yellow oval): classic indication that shingles are falling and it implies that the shingle(s) is beyond it's useful service life - recommend replacing

Some granular loss: the small rocks or pebbles embedded in the shingle protect the shingle from the ultraviolet rays of the sun. If they are missing the aging process is accelerated and they shingle dries an is no longer effective - consideration should be given to replacing the shingles



3. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Unable to Inspect: 25%:

Excessive roof pitch

4. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Approximate Age: 2001 - 17 years old: Roofing materials approaching the end of their useful service life - replacing the roofing materials would be a recommend improvement

5. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Ventilation: Roof and soffit vent(s)

6. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Plumbing Vents: Cast iron with lead cap

7. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Skylights: Metal frame and glass

8. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ Flashing: Asphalt composition and metal

9. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐ Valleys: Asphalt composition:

Vulnerable to ice and snow dams: water and snow melt that does not readily drain can cause an ice dam. Subsequently, when the ice begins to melt it follows the path of least resistance which is often under the shingles and into the living spaces. Consideration should be given to installing "heat tape" which can eliminate the risk

## Roof &amp; Chimney (Continued)

Valleys: (continued)

10. ☐ ☒ ☒ ☐ ☐ ☐ ☐ ☐

Gutters: Metal:

Debris: limits proper operation of drainage system and increases the chance of water damage. Debris also suggest that gutters may be improperly pitched (drain the wrong way)  
- recommend servicing

11. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐

Downspouts: Metal

12. ☐ ☒ ☐ ☐ ☐ ☐ ☐ ☐

Leader/Extension: Underground drainage

Furnace Chimney

13. ☐ ☐ ☒ ☐ ☐ ☐ ☐ ☐

Chimney: Metal pipe:

Rusting - monitor accordingly and replace if condition gets worse or if appliances(s) are replaced

14. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐

Chimney Flashing: Metal

15. ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐

Weather Cap: Metal

Fireplace, Furnace and water heater Chimney



## Roof &amp; Chimney (Continued)

16. ☐☐☒☐☐☐☐☐

Chimney: Brick:

Mortar joint(s) susceptible to water infiltration - monitor accordingly and repair if condition gets worse

17. ☒☐☐☐☐☐☐☐

Chimney Flashing: Cricket/saddle

18. ☐☐☐☒☐☐☐☐

Chimney Crown: Masonry:

Crack(s) (blue oval): these cracks typically get worse and allow water into the chimney - recommend repairs

Caulk missing (blue arrow): allows for water infiltration - recommend repairs

19. ☒☐☐☐☐☐☐☐

Weather Cap: Metal

## Garage

Side Garage

1 = Normal, 2 = Normal (Limited), 3 = Maintenance/FYI, 4 = Service/Repair, 5 = Safety Concern, 6 = Defective, 7 = Not Inspected, 8 = Not Present

1 2 3 4 5 6 7 8

1. Type of Structure: Attached Car Spaces: 2

2. ☐☒☐☐☐☐☐☐

Ceilings &amp; Walls: Drywall:

Personal property obstructing some view(s)

3. ☐☒☐☐☐☐☐☐

Floor &amp; Foundation: Concrete

4. ☐☐☒☐☐☐☐☐

Stairs/Railings: Concrete step(s):

Effective grab bars and handrail but probably would not comply with applicable codes

## Garage (Continued)

Stairs/Railings: (continued)

5. ☐☐☒☐☐☐☐☐ Windows: Double hung:

Screen(s) missing

6. ☐☐☒☐☐☐☐☐ Service Door: Metal:

Door closure needs adjusting/tensioning: closes too quickly and a safety concern for children

7. ☒☐☐☐☐☐☐☐ Overhead Doors: Insulated8. ☐☐☐☐☒☐☐☐ Door Operation: Mechanized door opener(s):

Reversing malfunction - door should reverse readily when sensors are obstructed

9. ☒☐☐☐☐☐☐☐ Lighting & Switches: Conventional lighting and switches10. ☐☒☐☐☐☐☐☐ Outlets & GFCI's: GFCI(s)

## Final Comments

The following summary does not included line items identified as "Not Inspected" or "Not Present"



## Summary

### Living Space

1. Entry/hallway/stairs Living Space Smoke Detector: Present (not tested): **Device(s) missing**
2. Living room Living Space Floor: Hardwood and area rug(s): **Sun stained (faded from exposure to sunlight)**
3. Living room Living Space Windows: Double hung: **Screen(s) missing**
4. Dining room Living Space Walls: Drywall, Wallpaper: **Amateur wallpaper application**
5. Dining room Living Space Windows: Double hung: **Screen(s) missing**
6. Dining room Living Space Lighting & Switches: Conventional lighting and switches: **Lighting not working**

### Bedroom

7. Red Bedroom Doors: Wood: **Door binds in framing**

### Kitchen

8. 1st floor Kitchen Windows: Double hung: **Seal(s) broken: the space between the panes of glass is broken allowing dirt and debris to "cloud" view - the only remedy is replacement**
9. 1st floor Kitchen Supply lines/Drain: Copper supply with PVC drainage: **Leaking (yellow oval)**
10. 1st floor Kitchen Cooking Appliances: Kenmore: **Verify that anti-tip bracket is present and installed properly**

### Bathroom

11. Master Bathroom Ceiling: Drywall: **Unusual pattern or stain on ceiling - discuss with owner**
12. Master Bathroom Supply lines/Drain: Copper supply with metal drain: **Faucet handle spins (yellow oval) - does not come to a stop**

**Drainage slow (yellow arrow)**

13. 2nd floor Bathroom Lighting & Switches: Conventional lighting & switches: **Lighting not working**
14. 2nd floor Bathroom Tub: Steel (porcelain finish): **Caulk around faucet to prevent water from entering wall cavity**

### Fireplace

15. Family room Fireplace Glass Doors/Screen: Screen only: **Screens do not prevent all embers from escaping the firebox and risks contact with combustible materials (yellow arrow)**

**Glass doors missing - installing this component adds a layer of fire safety which limits embers from contacting combustible materials. Doors will also limit or decrease air drafts**

16. Family room Fireplace Hearth: Raised: **Caulk missing**

### Laundry Area

17. 1st floor Laundry Room/Area Washer: Kenmore: **Mold (yellow arrow)**

**Front load washer: newer models have been know to have strong odors - recommend keeping door ajar and any trays open so moisture evaporates. Also, review manufacturer instructions and maintenance guidelines**

**Clothes inside - not operated**

18. 1st floor Laundry Room/Area Hoses: Rubber: **Rubber hoses have a tendency to leak - recommend replacing with braided supply hoses**

**Automatic washing machine water shut off valve recommended: if the current set-up develops a leak water will continue to flow since the valve is open. Installing an automatic shut off valve opens and closes the valve as needed**

### Basement

19. Lower level Basement Foundation: Concrete: **Cold joint(s): the result of two or more separate pours. It is best for all the concrete to be poured at one time. Cold joints can leak and can weaken the concrete though it usually does not adversely affect the structure - recommend monitoring for any leaks, changes or movement in this area and consider obtaining an analysis by a structural engineer**

## Summary (Continued)

- 20. Lower level Basement Doors: Wood: [Door missing?](#)
- 21. Lower level Basement Windows: Hopper: [Screen\(s\) missing](#)
- 22. Lower level Basement Stairs/Railings: Wood steps: [Handrail\(s\) missing \(very common\) - recommend installing](#)
- 23. Lower level Basement Smoke Detector: Wiring only: [Device\(s\) missing](#)
- 24. Lower level Basement Insulation: Fiberglass: [Verify that insulation is present - discussed with owner](#)

## Heating

- 25. Basement Furnace Humidifier: Aprilaire: [Damper door to remain open during heating season and closed during cooling season: failure to close damper in cooling season can result in an iced or frozen evaporative coil](#)
- 26. Basement Furnace Carbon Monoxide Detectors: Not present: [Missing - recommend installing appropriate detectors](#)
- 27. Basement Furnace Condensate Removal (AC system): PVC: [Poorly router in front of access panel](#)
- 28. 2nd floor Furnace Age (using ANSI date): 17 - ANSI year 1999: [Unit approaching the end of its useful service life - most units last 15-20 years](#)
- 29. 2nd floor Furnace Humidifier: Aprilaire: [Damper door \(yellow arrow\) to remain open during heating season and closed during cooling season: failure to close damper in cooling season can result in an iced or frozen evaporative coil](#)

[Discharge tube \(lime arrow\) dirty \(know source of air borne bacteria\) - recommend replacing](#)

[Filter scaled \(pink arrow\) - replace](#)

[Condensation leaking \(lime and blue ovals\)](#)

- 30. 2nd floor Furnace Carbon Monoxide Detectors: Not present: [Missing - recommend installing appropriate detectors](#)
- 31. 2nd floor Furnace Condensate Removal (AC system): PVC: [Poorly router in front of access panel](#)

## Electrical

- 32. Basement Electric Panel Panel: Square D: [Panels are best mounted on plywood sheet \(3/4"\), not scrap lumber - monitor and consider repairs if panel loosens or if moisture enters. Typically, not cost effective to repair unless necessary](#)
- 33. Basement Electric Panel Breakers: Single and double pole: [Double tap\(s\) WITHOUT availability of unused breaker\(s\): breakers are designed to have one conductor \(wire\) connected to it. A second wire connected to the lug \(screw\) is called a double tap and increases the chance of loosening the lug. Loose connections can arc \(spark\) and start an electrical fire - double taps are not advised and repairs are recommended](#)
- 34. Basement Electric Panel Branch Circuits: Conduit: [Conductor\(s\) improperly sized to breaker\(s\) - #14 on 20amp: each breaker is designed to correspond with a properly sized conductor. Undersized conductors and oversized breakers increase the risk of electrical failure and fire - recommend repairs by a licensed electrician](#)

## Plumbing

- 35. Main Plumbing Supply & DWV Floor Drain: Surface drain: [Recommend flushing drain with water to reseal the trap and prevent sewer gas orders from entering the living space](#)
- 36. Main Plumbing Supply & DWV Gas Service Lines: Black pipe: [Galvanic action: electrolytic corrosion \(electrolysis\) occurs when two dissimilar metals are in contact. The unlike metals cause a chemical reaction that results in the deterioration of one of them, Granted, the process may takes years but it will likely occur. Check for others...](#)
- 37. Basement Water Heater Draft Hood/Fan: Standard metal draft hood: [Not fastened \(yellow ovals\) - best if sheet metal screws are used to fix draft hood which will prevent unhealthy gases from escaping into living spaces](#)

[Draft was checked using a "smoke pen" and was okay \(yellow arrow\)](#)

- 38. Basement Water Heater T/P Valve & Drain Tube: Brass valve: [Discharge pipe opening is not within six inches of the floor](#)
- 39. Basement (at foundation wall) Sump Backup System: Not present: [Ask home owner if back up system is included in purchase](#)

## Summary (Continued)

- 40. Basement (at bathroom) Ejector Pump: Submerged: **Completely inaccessible (remove shelving unit)**
- 41. Basement (at bathroom) Ejector Backup System: Not present: **Back up systems are encouraged as they prevent costly repairs from water damage. Battery back up systems are common and are not too expensive. They are limited though to the charge on the battery. However, water pressure backup systems do not use or need electricity to perform. As the name implies water pressure is used to drain the pit in the event of an emergency. They are more expensive but "battery life" is no concern. Sump and/or ejector backup systems are recommended to protect system, components and personal property**

## Attic

- 42. 2nd level Attic Access Panel: Hardboard: **Skirt missing (yellow arrow): a perimeter barrier or skirt is typically installed at panel opening to prevent blown/loose insulation from falling from opening**

**Panel(s) not insulated: excessive heat loss (or heat gain) can pass through in uninsulated area - installing insulation over the panel opening or framing, not solely the panel, will eliminate a void in the insulation blanket**

- 43. 2nd level Attic Bathroom Vent(s): Not seen: **Bath vent(s) not visible: some contractors will install the vent between the attic floor joists and terminate it at a soffit vent. This also insulates the venting. This should be a dedicated vent and not shared as soffit vents are intended to allow air in which is contrary to bathroom fan venting. It is important to vent bathroom air to the outside because excessive moisture can cause a number of problems including damage to the structure, insulation and be a contributing cause of mold growth. It is also possible that the bathroom vent(s) are missing in which further review is recommended**
- 44. 2nd level Attic Appliance Venting: Kitchen hood: **Appliance vent(s) not visible: some contractors will install the vent(s) between the attic floor joists and terminate it at a soffit vent. This also insulates the venting. There should be a dedicated vent that is not shared because soffit vents are intended to allow air in which is contrary to bathroom fan venting. It is important to vent appliances to the outside because excessive moisture can cause a number of problems including damage to the structure, insulation and be a contributing cause of mold growth. It is also possible that the appliance vent(s) are missing in which further review is recommended**
- 45. 2nd level Attic Lighting & Wiring: Conventional lighting: **Lighting not working (bulbs?)**
- 46. 2nd level Attic Chimney (attic view): Metal pipe: **Combustion clearances inadequate (very common) - move insulation so it is not touching chimney**
- 47. 2nd level Attic Insulation Depth: 6-9": **Enough insulation to achieve an "R value" of 38 is recommended - most properties do not have the recommended amount of insulation**

## Exterior &amp; Grounds

- 48. Main Exterior Surface Windows: Double hung: **Mortar joint(s) likely to deteriorate over time (yellow oval): this is an excellent way for water and air to infiltrate the wall cavity - when needed, repair mortar to 1/4" of surface and top with high quality sealant. Do not create groove (finger swipe) with sealant as water will not drain on flat horizontal surface**

**Masonry is reverse pitched: water will flow towards the window instead of away - recommend repairs**

- 49. Main Exterior Surface Walks: Concrete: **Settled, consider mud-jacking: this process lifts or levels sunken concrete slabs. Holes are drilled through the slab and a concrete "slurry" is pumped under the slab until it levels out. The pumped liquid eventually hardens and the holes are patched**
- 50. Main Exterior Surface Window Wells: Locked: **Not readily accessible in the event of an emergency (yellow arrows)**

**Window well cover(s) should be rigid to support someone walking in the area (lime arrow)**

**Add rock/fill (pink arrow) - promotes better drainage**

- 51. Main Exterior Surface Vegetation: Trees and shrubs: **Tree limbs too close to the roof - trim to avoid limbs from damaging roof surface**
- 52. Main Exterior Surface Lighting & Switches: Conventional lighting: **Lighting not working**
- 53. Main Exterior Surface Outlets & GFCI's: GFCI(s): **GFCI(s) does not respond to mechanical tester: device may be defective or miswired - recommend repairs**

## Summary (Continued)

54. Main Exterior Surface Gas Meter: Exterior - North: Surface rust: this condition will only get worse and possibly cause a gas leak - consideration should be given to replacing the piping or at least sealing it with a rust inhibitor
55. Main Exterior Surface Hose Bibs: Present: Manifold for sprinkler system missing - discuss with owner

## Roof &amp; Chimney

56. Main Roof Surface Roof Surface: Shingles: Algae/fungi/moss (darker areas/streaks) on shingles (yellow arrow): this growth limits the drying process and accelerates aging - recommend using the appropriate methods to remove and clean area. Installing zinc strips at the ridge is a popular choice to remove algae as it does not flourish when the metal is present

Fiberglass mat or core exposed (yellow oval): classic indication that shingles are falling and it implies that the shingle(s) is beyond it's useful service life - recommend replacing

Some granular loss: the small rocks or pebbles embedded in the shingle protect the shingle from the ultraviolet rays of the sun. If they are missing the aging process is accelerated and they shingle dries and is no longer effective - consideration should be given to replacing the shingles

57. Main Roof Surface Approximate Age: 2001 - 17 years old: Roofing materials approaching the end of their useful service life - replacing the roofing materials would be a recommend improvement
58. Main Roof Surface Valleys: Asphalt composition: Vulnerable to ice and snow dams: water and snow melt that does not readily drain can cause an ice dam. Subsequently, when the ice begins to melt it follows the path of least resistance which is often under the shingles and into the living spaces. Consideration should be given to installing "heat tape" which can eliminate the risk
59. Main Roof Surface Gutters: Metal: Debris: limits proper operation of drainage system and increases the chance of water damage. Debris also suggest that gutters may be improperly pitched (drain the wrong way) - recommend servicing
60. Furnace Chimney Chimney: Metal pipe: Rusting - monitor accordingly and replace if condition gets worse or if appliances(s) are replaced
61. Fireplace, Furnace and water heater Chimney Chimney: Brick: Mortar joint(s) susceptible to water infiltration - monitor accordingly and repair if condition gets worse
62. Fireplace, Furnace and water heater Chimney Chimney Crown: Masonry: Crack(s) (blue oval): these cracks typically get worse and allow water into the chimney - recommend repairs

Caulk missing (blue arrow): allows for water infiltration - recommend repairs

## Garage

63. Side Garage Stairs/Railings: Concrete step(s): Effective grab bars and handrail but probably would not comply with applicable codes
64. Side Garage Windows: Double hung: Screen(s) missing
65. Side Garage Service Door: Metal: Door closure needs adjusting/tensioning: closes too quickly and a safety concern for children
66. Side Garage Door Operation: Mechanized door opener(s): Reversing malfunction - door should reverse readily when sensors are obstructed